


**Mill Creek Watershed**

Habitat Assessment Locations



**Habitat Score**

- Excellent >70
- Good 55 - 69
- Fair 43 - 54
- Poor 30 - 42
- Very Poor <30